


			P	
 6 003 43/49 6 004 43/49	-10°C...+70°C	-5°C...+40°C	250 V~ 5 V=	 2,5 mm²
 6 003 45 6 004 45	-10°C...+70°C	-5°C...+40°C	250 V~ 5 V=	 2,5 mm²
 6 003 42 6 004 42	-10°C...+70°C	-5°C...+40°C	16 A 250 V~ 5 V=	 2,5 mm²
 6 003 48	-10°C...+70°C	-5°C...+40°C	250 V~ 5 V= 1.0 A / 3.0 A	 2,5 mm²

6 003 43/45/49 - 6 004 43/45/49



6 003 42 - 6 004 42

